

| | | |
|-----------|-----------|----------|
| APPROVED | O.G. FIG. | |
| BY | CLASS | SUBCLASS |
| CRAFTSMAN | | |

1/22




FIG. 1

2/22




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D




FIG. 2E

3/22




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 3E

4/22




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 4D




FIG. 4E

5/22




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 5D




FIG. 5E




FIG. 5F

| | | |
|-----------|-----------|----------|
| APPROVED | C.G. FIG. | |
| BY | CLASS | SUBCLASS |
| CRAFTSMAN | | |

6/22




FIG. 5G




FIG. 5H




FIG. 5I

7/22




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 6D




FIG. 6E




FIG. 6F

8/22




FIG. 6G




FIG. 6H




FIG. 6I




FIG. 6J




FIG. 6K




FIG. 6L

9/22




FIG. 6M




FIG. 6N




FIG. 6O

10/22




FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D

| | | |
|-----------|-----------|----------|
| APPROVED | O.G. FIG. | |
| BY | CLASS | SUBCLASS |
| SKETCHMAN | | |

11/22




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D

| | | |
|-----------|-----------|----------|
| APPROVED | O.G. FIG. | |
| BY | CLASS | SUBCLASS |
| DRAFTSMAN | | |

12/22




FIG. 9

13/22




FIG. 10




FIG. 11

| | | |
|-----------|-----------|----------|
| APPROVED | O.G. FIG. | |
| BY | CLASS | SUBCLASS |
| DRAFTSMAN | | |

14/22




FIG. 12




FIG. 13

15/22




FIG. 15




FIG. 16




FIG. 14




FIG. 17

16/22




FIG. 21




FIG. 18

17/22




FIG. 23

FIG. 24





FIG. 22

FIG. 25



18/22




FIG. 29




FIG. 27




FIG. 28




FIG. 26

19/22




FIG. 33




FIG. 31




FIG. 32




FIG. 30

20/22




FIG. 37




FIG. 35




FIG. 36




FIG. 34

21/22




FIG. 41




FIG. 39




FIG. 40




FIG. 38

22/22




FIG. 45




FIG. 43




FIG. 44




FIG. 42